

Form 574-6 - Revised May, 1913
 U. S. Department of Agriculture
 FOREST SERVICE

A1

~~Chippewa~~ NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 Mer. 5th

SEC. Corner common to Sections

36, 31, 1, and 6

Corner consists of a cap in cement (not) in place

State condition new

Dimensions above ground 7" at base 2 1/4" in inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

T. 147			
5.36	R. 27	5.31	R. 26
S. 1		S. 6	
N	W	E	S

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 147 R. 26 S. 31	T. 147 R. 26 S. 6	T. 147 R. 27 S. 1	T. 147 R. 27 S. 36
B. T.	B. T.	B. T.	B. T.

Species	<u>d. p.</u>	<u>d. p.</u>	<u>w. p.</u>	<u>d. p.</u>
Diameter	<u>2 1/2"</u>	<u>1 1/2"</u>	<u>1 1/2"</u>	<u>1 1/2"</u>
Bearing	<u>N. 51° E.</u>	<u>S. 43° E.</u>	<u>S. 54° W.</u>	<u>N. 60° W.</u>
Distance	<u>144</u>	<u>143</u>	<u>219</u>	<u>237</u>

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


B. Balfe
 (Signature)

E. J. Jader
 (Title)

1937
 (Date)

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant Give any farther facts which will aid in finding this



(Make sketch of topography near Corner)

R. 26 Mer. 54

U. S. Department of Agriculture

FOREST SERVICE

Handwritten mark resembling the letter 'A' with a horizontal line through it.

477223 NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 47 R. 36 Mer.

Corner common to Sections 31, 31, and 31



Corner consists of a stone (not) in place State condition good

Dimensions above ground 7 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. R. Mer.

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5th Mer.

500 Corner common to Sections
36, 31, 1, and 6

Corner consists of a peg in cement (not) in place
State condition new

Dimensions above ground 77 24 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

T147		R26	
536	531		
R27	51	56	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147
R26
531
BT

T147
R26
56
BT

T147
R27
51
BT

T148
R27
50036
BT

Species	JP	JP	WP	JP
Diameter	8	7	5	7
Bearing	N51°E	S43°E	S54°W	N60°W
Distance	44	43	29	32

Do you believe this to be a genuine Land Office Corner? yes
If not, why? _____


(Signature)

(Date)

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147N R. 26 W. 5th Mer.