

U. S. Department of Agriculture

FOREST SERVICE

T3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 26W 5th Mer.

C 1/4 Corner common to Sections

30, and

Corner consists of a Wood post in place


State condition Good

Dimensions above ground 4" x 4" x 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E





NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



B.T.

B.T.



Species Spruce Spruce

Diameter 6" 6"

Bearing N 31E S 50E

Distance 25 15

Do you believe this to be a genuine Land Office Corner? No

If not, why? Forest Service corner

Walter Haberle

WALTER HABERLE

(Signature)

Project Assistant

3/6/41

(Date)

(Title)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a Bearing Tree



(Make sketch of topography near Corner)

T. R. Mer.