

U. S. Department of Agriculture
FOREST SERVICE

53

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5th Mer.

1/4 Corner common to Sections

6, and 7.

Corner consists of a Elm (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S-7			
B.T			

Species d. Pine D.J. PINE.

Diameter 14" 12"

Bearing S-65°W N-16°W

Distance .14 .24

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Balke

(Signature)

Leader


(Title)

1936

(Date)

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 R. 26 Mer. 5-11