

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

04

T. 147N R. 26W 5th Mer.

1/16 #8 Corner Station to Section 30, and

Corner consists of a Wood post in place

State condition Good

Dimensions above ground 4" x 4" x 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/16	#8		
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 #8			
S. 30			
B. T.			

Species **Jack Pine**

Diameter **6**

Bearing **N 36W**

Distance **29**

Do you believe this to be a genuine Land Office Corner? **NO**

If not, why? **Forest Service Corner**

*Walter Haberk*  
WALTER HABERLE

Project Assistant


3/6/41  
(Date)

(Time)

Handwritten notes on a ruled page.

Corner again.

Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a Bearing Tree



(Make sketch of topography near Corner)