

U. S. Department of Agriculture  
FOREST SERVICE

7-5

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5<sup>th</sup> Mer.

1/4 Corner common to Sections

33, and 30

Corner consists of a Tree (not) in place

State condition 30 1/2

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|            |            |  |  |
|------------|------------|--|--|
|            |            |  |  |
| <u>3.7</u> | <u>5.5</u> |  |  |

Species White Birch

Diameter 4"

Bearing S. 70° W. 40 FT

Distance 33 30

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

(Signature)

1936  
(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

5th

R. 26

T. 147