

Form 874-0—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

2-7

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. *147N* R. *R6W* *5th* Mer.

1/4 Corner common to Sections
 _____, *32*, and *5*

Corner consists of a *woodpost* (not) in place
 State condition *poor*

Dimensions above ground *7" x 3" x 18"* inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.
 CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>147N</i> <i>R6W</i>	<i>147N</i> <i>R6W</i>		
<i>B.T.</i>	<i>B.T.</i>	<i>B.T.</i>	

Species *Fern.* *Fern.* *Tomsth*

Diameter *2"* *12"* *8"*

Bearing *N6°W* *N0* *S16°E*

Distance *1.03* *1.12* *.76*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

Walter H. Hule
 (Signature)

9/7/38
 (Date)

Leadon
 (Title)

128

