

U. S. Department of Agriculture
FOREST SERVICE

47

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5th Mer.

1/4 Corner common to Sections
8, and 17

Corner consists of a Tam (net) in place

State condition new

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|----------|------|--|--|
| S- 17 | | | |
| B.T. | B.T. | | |

Species N.P. STAR TAVERN \$10.00

Diameter 22" 16"

Bearing S. 12° E N. 47° E

Distance 33 31

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Balke

(Signature)

Leader

(Title)

1/4/37
(Date)

LOW LAND, N. SIDE OF RIDGE

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 7 N. R. 26 Mer. 5th