

U. S. Department of Agriculture
FOREST SERVICE

A7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14 R. 26 Mer. 5 1/2

Corner common to Sections

32 and 3

Corner consists of a wood post (not) in place

State condition gone

Dimensions above ground 2 1/2 x 1 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

7117 B36	7147 B36		
87	17	B7	

Species Large tree trunk

Diameter 8 18 8

Bearing N66° N60° S16°E

Distance 103 118 76

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Walter B. Cole
(Signature)


9/1/38
(Date)

Walter B. Cole
(Title)

.....
.....
.....
.....
.....
.....
.....
.....
.....
.....

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147 R. 26 Mer. 5-1