

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

7-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5th Mer.

$\frac{1}{4}$ Corner common to Sections

28, and 29.

Corner consists of a Cedar (not) in place

State condition New

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION





N W S E NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species J. PINE J. PINE

Diameter 8" 10"

Bearing N. 47° W S. 61° E

Distance .38 .46

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

B. Alpe

(Signature)

1937

(Date)

S. Loder

(Title)

Small Clearings

On NW corner of

Corner again.

Give any further facts which will aid in finding this


chains distant. 30

from which this Corner bears

side of

tree 10 inches diameter, on the S.

Metal Location Poster is on a N.Pine.



(Make sketch of topography near Corner)

Mer.

5-TH

R. 26

T. 147

T-1-A

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 E. 6 Mer.

1/4 Corner common to Sections
28, and 29

Corner consists of a Red (not) in place



State condition New

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T-147
 286
 S-29

T-147
 286
 S-28

BT

BT

Species J. PINE J. PINE

Diameter 9 1/2" 10 1/2"

Bearing N. 47° W S. 61° E

Distance .38 .46

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Balk
 (Signature)

1936
 (Date)

Marked
 (Title)

Faint, illegible text at the top of the page, possibly bleed-through from the reverse side.

*Farmer is located at small clearing -
N-W corner of small clearing -*

Corner again.

Give any further facts which will aid in finding this

1.30 LKs - chains distant.


from which this Corner bears

side of

tree 10 inches diameter, on the *South*

Metal Location Poster is on a

N-line



(Make sketch of topography near Corner)