

U. S. Department of Agriculture  
FOREST SERVICE

R-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5th Mer.

Sec. 20, 21, 28, and 29 Corner common to Sections

Corner consists of a 1. PINE (not) in place  
State condition New

Dimensions above ground 3.04 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S-	S-	S-	S-
20	29	28	21

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

B.T.	B.T.	B.T.	B.T.
------	------	------	------

Species	<u>N.P. STUMP</u>	<u>N.P. STUMP</u>	<u>FALLEN N.PINE</u>	<u>N.PINE</u>
Diameter	<u>2.8"</u>	<u>2.8"</u>	<u>2.4"</u>	<u>2.4"</u>
Bearing	<u>N. 45° W</u>	<u>N. 76°</u>	<u>S. 47° W</u>	<u>S. 33° E</u>
Distance	<u>.05</u>	<u>.30</u>	<u>.40</u>	<u>.42</u>

Do you believe this to be a genuine Land Office Corner? YES

If not, why? \_\_\_\_\_

Balpe

(Signature)


1/13/37  
(Date)

Reader  
(Title)

Faint, illegible text at the top of the page, possibly bleed-through from the reverse side.

Corner again.

Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 142 R. 26 Mer. 5th