

U. S. Department of Agriculture
FOREST SERVICE

P-9

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 Mer. 5th

1/4 Corner common to Sections

20, and 21

Corner consists of a Farm (not) in place

State condition New

Dimensions above ground 20 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

M	A	R	K
---	---	---	---

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S-21			
B.T.			

Species N-PIKE FRUIT

Diameter 2 1/4"

Bearing N-57°E

Distance .75

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Balke
(Signature)

Leader
(Title)

1927
(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

From which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147. R. 26 Mer. 5th