

U. S. Department of Agriculture  
FOREST SERVICE

G9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N. R. 26W. 5<sup>th</sup> Mer.

Quarter Corner common to Sections  
8, 9, and

Corner consists of a Wood Stake (not) in place  
State condition Good

Dimensions above ground 16 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	$\frac{1}{4}$ S <sub>8</sub>	$\frac{1}{4}$ S 9	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	$\frac{1}{4}$ S <sub>8</sub>	<u>Stump?</u>	
	<u>B.T.</u>	<u>B.T.</u>	

Species Spruce Basswood

Diameter 10"

Bearing N47°W S84°E

Distance 36L 54L

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? Yess. B.T. are original. But  
Stake has been moved to right  
hand side of road going South

Hubert J. Fulmer  
(Signature)

Oct 11, 1934  
(Date)


Sub. Foreman  
(Title)

41

Handwritten notes on a series of horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this  
..... chains distant.  
from which this Corner bears  
side of .....  
tree ..... inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)

T 141N R. 26W S 14 Mer.

U. S. Department of Agriculture

FOREST SERVICE

69

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 177N R. 26W 5th Mer.

1/4 Corner common to Sections 8, and 9

Corner consists of a wood stake (not) in place



State condition good

Dimensions above ground 16 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species 5766 Basswood

Diameter 10

Bearing N47°W 584 OF

Distance 36 54

Do you believe this to be a genuine Land Office Corner?

If not, why? 24

(Signature)


(Date)

(Title)

41

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. H. R. Mer. 5-77

U. S. Department of Agriculture  
FOREST SERVICE

6-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 26 W. 5th Mer.

Corner common to Sections

8, and 9

Corner consists of a wood stake (not) in place


State condition good

Dimensions above ground 16 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner?

If not, why? \_\_\_\_\_


(Signature)

(Date)

(Title)

Metal Location Poster is on a \_\_\_\_\_  
 tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_  
 side of \_\_\_\_\_  
 from which this Corner bears \_\_\_\_\_  
 chains distant.

Give any further facts which will aid in finding this  
 Corner again.



(Make sketch of topography near Corner)

T. R. Mer.