

U. S. Department of Agriculture  
FOREST SERVICE

E-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5<sup>th</sup> Mer.

sec. Corner common to Sections

3, 4, 9, and 10

Corner consists of a Tam. in place


State condition Good

Dimensions above ground Covered By Road inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE


Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

NONE

LOCATED



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Restablished BY

COUNTY Surveyor

B. Baker

(Signature)

Leader

(Title)

1936

(Date)

GOOE OF TRUE COR.

ROAD MARK. POST "X 40"

IN CENTER OF ROAD.

CHAIN N. OF INTERSECTION

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147 R. 26 Mer. 5th

U. S. Department of Agriculture  
FOREST SERVICE

2-13

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 Mer. 5

SEC Corner common to Sections  
3, 4, 9, and 16

Corner consists of a Stone (not) in place


State condition Good

Dimensions above ground covered by Rock Inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Corner was established

By County Surveyor

Bulke

(Signature)

1936


(Date)

Surveyor

(Title)

Corner again.  
Tweeter is about 100 feet  
North of Road intersection  
to be in road bed  
Road Marks - 50 feet - 100 feet  
40" 000 of Tweeter -

Metal Location Poster is on a  
tree inches diameter, on the  
side of \_\_\_\_\_  
from which this Corner bears  
\_\_\_\_\_ chain distant.  
Give any further facts which will aid in finding this



(Makes sketch of topography near Corner)