

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

53

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 26W 5th Mer.  
1/16 #5

Corner common to Sections

30

, and

Corner consists of a Wood post (not) in place  
State condition Good

Dimensions above ground 4"x4"x30# inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/16 #5			
---------	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 #5 #30
----------------

1/16 #5 #30
----------------

--

--

B.T.
------

B.T.
------

--

--

Species Red Pine

Diameter 12

Bearing N 88 E

Distance 13

Do you believe this to be a genuine Land Office Corner? No

If not, why? Forest Service Corner

Walter Haberle

WALTER HABERLE

(Signature)


Project Assistant

3/5/41

(Date)

(Title)

Metal Location Poster is on a **Bearing Tree**  
 tree ..... inches diameter, on the  
 side of .....  
 from which this Corner bears  
 chains distant.  
 Give any further facts which will aid in finding this  
 Corner again.



(Make sketch of topography near Corner)