

U. S. Department of Agriculture
FOREST SERVICE

25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5th Mer.

1/4 Corner common to Sections
3, 10, and

Corner consists of a DeK (not) in place


State condition None

Dimensions above ground 30" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



BT BT

Species Pine Stumps Pine Stumps

Diameter 14" 12"

Bearing S 15° W N 75° W

Distance 37 63

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Balke
(Signature)


Leader
(Title)

7/36
(Date)

Handwritten notes on a series of horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this chains distant. from which this Corner bears side of tree inches diameter, on the Metal Location Poster is on a



(Make sketch of topography near Corner)