

U. S. Department of Agriculture
FOREST SERVICE

817

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 177 R. 26 Mer.

1/4 Corner common to Sections
22, and 23

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

BT		BT	
----	--	----	--

Species Lind Elm

Diameter 6" 5"

Bearing S 24 W N 33 E

Distance 258 1210 558 3630

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

66 3
55 25
350 40
330 150
150

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R. Mer.