

U. S. Department of Agriculture  
FOREST SERVICE

117

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 Mer.

Section 10 Corner common to Sections

14, 15, 22, and 23

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

137			
-----	--	--	--

Species Aspen Aspen Aspen Aspen

Diameter 5" 5" 5" 5"

Bearing S57W N69W S70E N67E

Distance 121 302 82 92

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

(Signature)

(Date)

(Title)

Blank lined area for notes at the top of the page.

Corner again.

Give any further facts which will aid in finding this  
chain distant.  
From which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)