

U. S. Department of Agriculture

FOREST SERVICE

A17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5TH. Mer.

Section

Corner common to Sections

34, 35, 3, and 2

Corner consists of a wood post (not) in place

State condition in ground good

Dimensions above ground 4'-4"-30"

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Sec. 3			
BT			

Species Spr. Stub

Diameter 4"

Bearing S34W

Distance 74 lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Could not find any original BT perhaps County Corner

Walter Haberle

(Signature)

Leader


7/18/39

(Date)

(Title)

(Make sketch of topography near Corner)

T. 147 R. 26 S. 5 Mer. A-17



Metal Location Poster is on a Cedar Post

4 inches diameter, on the West

side of Corner

from which this Corner bears East

12 LKS. chains distant.

Give any further facts which will aid in finding this Corner again.