

U. S. Department of Agriculture
FOREST SERVICE

713

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 5th Mer.
Sec.

Corner common to Sections

2, 3, 10, and 11

Corner consists of a Iron Pipe (not) in place


State condition Good

Dimensions above ground 6' inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



B.T. B.T. [] []

Species Maple Maple
Diameter 14" 18"
Bearing S. 36° E N 60° W
Distance .10 .76

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? _____

Balke

(Signature)


Reader

(Title)

1936.

(Date)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 R. 26 5th E-17 Mer.