

U. S. Department of Agriculture
FOREST SERVICE

219

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 Mer.

4 Corner common to Sections
2, and 35

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar Cedar

Diameter 14 10

Bearing N 92° W S 44° W

Distance 38 58.5'

Do you believe this to be a genuine Land Office Corner? No

If not, why? No BTs or anything to indicate cor. Fire went through in the 20s

(Signature) [Signature]

(Date) _____

(Title) _____

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

		Sec.	
		Sec.	

(Make sketch of topography near Corner)

T. R. Mer.