

U. S. Department of Agriculture
FOREST SERVICE

119

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *147* R. *26* Mer. *5th*

4 Corner common to Sections
26, and *35*

Corner consists of a *Nothing* (not) in place
State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter *no* *13 1/2*

Bearing *no* *corner*

Distance *no* *top on trees*

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Joseph L. Lanch
(Signature)

8-19-58
(Date)

(Title)

Blank lined area for notes at the top of the page.

Corner again.

Give any further facts which will aid in finding this

chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)