

U. S. Department of Agriculture  
FOREST SERVICE

221

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 Mer.

Corner common to Sections

1, 2, 35, and 36

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing-Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

B7			

Species Balsam Birch Spruce

Diameter 7" 10" 2"

Bearing S 27 1/2 E N 23 1/4 S 43 1/4

Distance 63.3 47.8 59.5'

Do you believe this to be a genuine Land Office Corner?

If not, why? NO TRACE OF

COR B.T.S OR TAG

(Signature) py E

(Date)

(Title)

U. S. Department of Agriculture

FOREST SERVICE

NATIONAL FOREST

# CORNERS OF THE PUBLIC SURVEY

Corner No. \_\_\_\_\_  
County \_\_\_\_\_ State \_\_\_\_\_

Corner No. \_\_\_\_\_ in place \_\_\_\_\_  
Corner again.

Give any further facts which will aid in finding this  
corner.

Chain distant \_\_\_\_\_  
from which this corner bears \_\_\_\_\_

side of \_\_\_\_\_

tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_

Metal Location Poster is on a \_\_\_\_\_


(Make sketch of topography near Corner)

Map

R

T