

U. S. Department of Agriculture
FOREST SERVICE

A23

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 17 S. R. 26 Mer.

4 Corner common to Sections
1, and 36


Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar SPRUCE

Diameter 12 11

Bearing N17 1/2 W S4 E

Distance 43.2 44.7

Do you believe this to be a genuine Land Office Corner? _____

If not, why? No could not find any BTs

Stacey
County Court House
Surveyors Record page # 8
(Signature)

(Date)

(Title)

1894

Corner again. Tap on the reads 18 on 1/4 5

Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of Road tree 20 inches diameter, on the Metal Location Poster is on a

4) Pine (6) = 57

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R. Mer.