

U. S. Department of Agriculture
FOREST SERVICE

T-U

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 26 S. 5 Mer.

M.C. Corner common to Sections

25, and 30

Corner consists of a granite (not) in place



State condition Just Erected

Dimensions above ground 11 - 28 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W E

NW SW SE NE


Mound of ~~is located~~

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



MC



Species W. Oak J. Pine

Diameter 12 5 1/2

Bearing N 41 3/4° E N 81 1/4° W

Distance 141 141

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Balkin


(Signature)

1936
(Date)

Stadler
(Title)

THE PROPERTY OF THE U. S. GEOLOGICAL SURVEY
 OFFICE OF THE CHIEF OF BUREAU
 WASHINGTON, D. C.

Corner again.
 Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Make sketch of topography near Corner)