

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

81

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5th Mer.

Quarter Corner common to Sections
24, and 19

Corner consists of a Brass cap on (not) in place

State condition iron pipe

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

319	324	324	
-----	-----	-----	--

BT	BT	BT	
----	----	----	--

Species Cedar Cedar Spruce

Diameter 5 5 10

Bearing S74E N61W N68W

Distance 31 16 17

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Walter Haberle

(Signature)

11/27/39

Leader

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears


side of

tree inches diameter, on the

Berring trees

Metal Location Poster is on a

The cedar



(Make sketch of topography near Corner)

T. 147 R. 27 Sth Mer.