

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST G-1



CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

14 Corner common to Sections  
12, and 7

Corner consists of a Iron Pipe (not) in place  
State condition just buried


Dimensions above ground 2-27 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N.P. N.P.  
Diameter 8" 10"  
Bearing N-17°E S-60°W  
Distance 24 26

Do you believe this to be a genuine Land Office Corner?  
If not, why? J

1936  
(Date)

(Signature)

(Title)

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 142N R. 27W Mer. 5769