

U. S. Department of Agriculture
FOREST SERVICE

N-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

1/4 Corner common to Sections

18, and 19

Corner consists of a stone (not) in place


State condition new

Dimensions above ground 1" - 28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species w. oak w. oak

Diameter 5

Bearing N70 1/2 E S33 1/2 E

Distance 18 24

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147 N. R. 27 E. S. 14 Mer.

U. S. Department of Agriculture
FOREST SERVICE

N-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *147N* R. *27w* *5th* Mer.

1/4 Corner common to Sections

18, and *19*

Corner consists of a *Iron Pipe* (not) in place


State condition *new*

Dimensions above ground *1" - 28"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *W. Oak W. Oak*

Diameter *5 5*

Bearing *N 10 1/2 E S 52 1/2 E*

Distance *78 64*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____


(Signature)

(Date)

(Title)

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 N R. 27 W 5th Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

*Copied
Filed
5/31.
N-3*

----- NATIONAL FOREST -----

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 S. 5 Mer.

----- Corner common to Sections
18, 19, and -----

Corner consists of a no post (not) in place
State condition -----

Dimensions above ground ----- inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

(Signature)

(Date)

(Title)

Corner of the Public Survey
 Section of the Public Survey
 Corner of the Public Survey

26 * W P one chain N of
 Corner again.

Give any further facts which will aid in finding this
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Tower is on a

Sec. 19			Sec.
D 4 sec. 19			
Sec. 8			Sec.

(Make sketch of topography near Corner)

Posted
N3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 27 W. Mer.

1/4 Corner common to Sections
10, and 19


Corner consists of a Squated stake in place
State condition Good

Dimensions above ground 3 ft. high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. P.

Diameter 2 1/2"

Bearing N 11° E

Distance 40 ft.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

W. Banks
(Signature)

9/17/34
(Date)

T. F.
(Title)

VENUE

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST N-3

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 21 W S11 - Mer.

1/4 Corner common to Sections

18 and 19

Corner consists of a JIP (not) in place



State condition JIP

Dimensions above ground 1" 28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S18	S19		
BT	BT		

Species W oak W oak

Diameter 5" 5"

Bearing N40 1/2 E S57 1/2 E

Distance 78 64

Do you believe this to be a genuine Land Office Corner? *GH*

If not, why?

(Signature)


(Date)

(Title)

71

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)