

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST P-5

CORNERS OF THE PUBLIC SURVEY

T. 187N R. 27W 5th - Mer.

1/4 Corner common to Sections

19, and 20
Corner consists of Iron Post in place

State condition

Dimensions above ground 1' - - - inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1/4		
S	19	S20	
	19	20	
N	W	E	

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

No BT's available.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Yes

(Signature)

(Date)

(Title)

UNITED STATES DEPARTMENT OF AGRICULTURE
BUREAU OF LAND MANAGEMENT

Corner again.


Give any further facts which will aid in finding this chains distant.

From which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 142N R. 23W 57N-Mer.

U. S. Department of Agriculture
FOREST SERVICE

85
R

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

1/4 Corner common to Sections

19, and 20

Corner consists of a iron pipe (not) in place



State condition just located

Dimensions above ground 1--25" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

(Signature)

(Date)

(Title)

78

02

◇

19

574

276

1271

U. S. Department of Agriculture
FOREST SERVICE

8-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.



14 Corner common to Sections
19, and 20

Corner consists of a ~~stone~~ (not) in place
State condition just created

Dimensions above ground 1--78" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____
 Diameter _____
 Bearing _____
 Distance _____

Do you believe this to be a genuine Land Office Corner? yes
If not, why? _____

(Signature)

(Date)

(Title)

78

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 142 N R. 27 W Mer. 5 H