

U. S. Department of Agriculture
FOREST SERVICE

Posted
05

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *147 N.* R. *27 W.* Mer.


N 1/4 Corner common to Sections
19, and *20*

Corner consists of a *Squared Cedar post (not)* in place
State condition *Fair*

Dimensions above ground *4" dia.* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *W. Cedar* *W. Cedar*

Diameter *6"* *6"*

Bearing *? fallen* *S.E.*

Distance *?* *11 ft.*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

W. Banks
(Signature)

9/17/34
(Date)

T.F.
(Title)

Corner again.

Give any further facts which will aid in finding this


..... chains distant.

from which this Corner bears

side of

tree..... inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

0-5

CHIPPENAWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 27 W. 5th Mer.
16 Corner common to Sections

19, and 20

Corner consists of a Sassa stake (not) in place
State condition

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N. W. S. E.

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>N.W.</u>	<u>S.E.</u>		

Species Cedar 2 1/2" dia

Diameter 6"

Bearing N42°E 351°E

Distance 13 ch. 14 ch.

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

James W. Hamala
(Signature)

June 1, 1905
(Date)

Forest Ranger
(Title)

786

Continued on back of page

U.S. GEOLOGICAL SURVEY

Topographic map of the area

of the area shown on the map

is shown on the map

of the area shown on the map

of the area shown on the map

of the area shown on the map

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



Topographic map of the area

U. S. Department of Agriculture
FOREST SERVICE

P.
0-5

CHIPPewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 27 W 5th Mer.

N 1/16 Corner common to Sections
19, and 20

Corner consists of a cedar stake (not) in place


State condition

Dimensions above ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar Cedar windfall

Diameter 6" 6"

Bearing N 42° E S 54° E

Distance .13 ch. .14 ch.

Do you believe this to be a genuine Land Office Corner?


If not, why?

J. J. [Signature]
(Date) June 11 1935 (Signature)
J. J. [Signature]
(Title)

Handwritten notes on a grid background, including the word "CORNER" and other illegible text.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)