

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147N R. 22W 5th Mer.

1/4 Corner common to Sections 32, and 5

Corner consists of a Iron Post (not) in place



State condition Just Erected

Dimensions above ground 2' 8" 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Torus Torus

Diameter 4" 4"

Bearing N-12 1/2 W S-34 1/2 W

Distance 2 1/2 Lks 4 Lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)

1936
(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 127N R. 27W 5th Mer.

U. S. Department of Agriculture
FOREST SERVICE

A-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147, R. 27, Mer. 5

1/4 corner Corner common to Sections 32, and 5

Corner consists of a ~~stone~~ (stone) in place
State condition just created

Dimensions above ground 2"-8"-28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Monument			
1/4	5	32	
	5	5	
N	W	S	E

Marked			
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 147	T 147		
R 27	R 27		
S 32	S 5		
BT	BT		

Species Tam Tam

Diameter 4" 4"

Bearing N 125° W S 39° W

Distance 2.8 lks 14

Do you believe this to be a genuine Land Office Corner? *yes*


If not, why? _____

(Signature)

(Date)

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 R. 27 Mer. 5

U. S. Department of Agriculture
FOREST SERVICE

A-7

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W Mer. 5th

1/4 Corner common to Sections
32, and 5



Corner consists of a Iron Post (not) in place
State condition Just Erected

Dimensions above ground 2" 8" 28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T-148N	T-147N		
R-27W	R-27W		
S-32	S-32		
BT	BT		

Species Tom Tom

Diameter 8" 4"

Bearing N-12°W S34°W

Distance 2 1/2 LKs 14 LKs

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


(Signature)

1936
(Date)

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147N R. 27W 5th Mer.