

## U. S. Department of Agriculture

## FOREST SERVICE

Chippewa NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5<sup>th</sup> Mer.Sec. 20, 21, 28, and 29  
Corner common to SectionsCorner consists of a Brass capped pipe (not) in place  
State condition good

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

NW	NE	SE	SW

Species	<u>Ash</u>	<u>Aspen</u>	<u>Ash</u>	<u>Ash</u>
Diameter	<u>6"</u>	<u>9"</u>	<u>6"</u>	<u>4"</u>
Bearing	<u>N 23 W</u>	<u>N 45 E</u>	<u>S 39 E</u>	<u>S 45 W</u>
Distance	<u>42 lks.</u>	<u>7 lks.</u>	<u>9 lks.</u>	<u>26 lks.</u>

Do you believe this to be a genuine Land Office Corner? yes  
If not, why? \_\_\_\_\_J. P. Hemola  
(Signature)T. F.  
(Title)5/2/35.  
(Date)

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears

side of

tree inches diameter, on the

~~Metal Location Poster is on a~~ *Not Posted*



(Make sketch of topography near Corner)

T. 147 R. 27 Mer. 5-74

**U. S. Department of Agriculture**  
**FOREST SERVICE**

*Posted*  
*R-9*

*Chippewa* NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. *197 N.* R. *27 W.* Mer.

Section Corner common to Sections

*20, 21, 28, and 29*

Corner consists of a *Pipe with brass cap (not)* in place  
State condition *Good* *Also cedar post 4"x4" and 4.5' high*

Dimensions above ground *8" high* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species *Aspen* *Ash* *Ash* *Ash* *Em*

Diameter *10"* *6"* *10"* *10"* *19c*

Bearing *E* *SW* *N* *SE* *Type*

Distance *10ft* *25ft* *30ft* *30ft*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_


*W. Banks*  
(Signature)

*9/17/34*  
(Date)

*T. F.*  
(Title)

Corner again.  
Located in a mixed hardwood  
type

Metal Location Poster is on a  
tree ..... inches diameter, on the  
side of .....  
from which this Corner bears  
..... chains distant.  
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 121N. R. 27W. Mer.

U. S. Department of Agriculture

FOREST SERVICE

B-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.  
Section

Corner common to Sections  
20, 21, 28, and 29

Corner consists of a Iron pipe (not) in place

State condition good

Dimensions above ground 1"12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

20	29	28	21
----	----	----	----

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147N  
R27W  
S28

T147N  
R27W  
S21

T147N  
R27W  
S29

T147N  
R27W  
S20

BT

BT

BT

BT

Species Ash Aspen Ash Maple

Diameter 8" 6" 4" 8"

Bearing S35E N46E S45W N24W

Distance .10 .6½ .26 .47

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Walter Haber<sup>le</sup>

(Signature)

2/13/40

(Date)

Leader

(Title)

80

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the in Sec. 29-29

Metal Location Poster is on a The bearing trees



(Make sketch of topography near Corner)