

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

M-9

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5<sup>th</sup> Mer.

M.C.

Corner common to Sections

17, and 16

Corner consists of a Iron Pipe (w) in place



State condition New

Dimensions above ground 1" x 20" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S-17	S-17		
B.T	B.T		

Species TAM TAM

Diameter 6" 6"

Bearing S-38W N-52W

Distance .54 .43

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

(Signature)

1936.

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

57

R. 27

T. 147