

U. S. Department of Agriculture  
FOREST SERVICE

C-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. R7W 5th-Mer.

1/4 Corner common to Sections

5 and 4

Corner consists of a F.P. (not) in place



State condition JOE

Dimensions above ground 1" 2 1/2" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spine Spine

Diameter 15" 14"

Bearing S63 1/4 E S10 3/4 W

Distance 24 37 1/2

Do you believe this to be a genuine Land Office Corner Yes

If not, why? \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

(Signature)


(Date)

(Title)

*[Faint, illegible text on ruled lines]*

Corner again.

Give any further facts which will aid in finding this  
chain distant.  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

C9  
Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

1 Corner common to Sections  
S. 1, N. 1, sec. 5, and N. 1, S. 1, s. c. 4


Corner consists of a Wooden stake (not) in place  
State condition Good

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Bound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_


Do you believe this to be a genuine Land Office Corner? No

If not, why? No bearing trees

4/20/35  
(Date)

*John M. Stephens Jr.*  
(Signature)  
*Technical Examiner*  
(Title)

Corner again.  
 Give any further facts which will aid in finding this  
 chain distant.  
 from which this Corner bears S 45° W  
 inches diameter, on the  
 side of Tree  
 Metal Location Poster is on a  
 Black Sparrow



(Make sketch of topography near Corner)

Form 874-G—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

Chippewa NATIONAL FOREST

59

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

Quarter Corner common to Sections 4 and 5

Corner consists of a Iron pipe (not) in place  
 State condition good

Dimensions above ground 1" 12" inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION				DIAGONAL POSITION			
	1/4						
	S5/34						
N	W	S	E	NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147N R27W S4	T147N R27W S5		
BT	BT		

Species	Spruce	Spruce		
Diameter	5"	4"		
Bearing	S63E	S11W		
Distance	.24	.37		

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Walter Heberle

(Signature)

2/29/40  
 (Date)

Project Asst.  
 (Title)

U. S. DEPARTMENT OF THE INTERIOR

Geological Survey

CORNERS OF THE PUBLIC SURVEY

Give any further facts which will aid in finding this corner again.


Chain distant.

From which this corner bears

side of

tree inches diameter, on the

Metal Location Poster is on the bearing trees



(Make sketch of topography near corner)

U. S. Department of Agriculture  
FOREST SERVICE

C-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27W 5th Mer.

Quarter

Corner common to Sections

4, and 5

Corner consists of a Iron Pipe (not) in place

good


State condition

Dimensions above ground 1"12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147N
R. 27W
S4

T147N
R27W
S5

--

--

BT
----

BT
----

--

--

Species Spruce Spruce

Diameter 5" 4"

Bearing S63E S11W

Distance .24 .37

Do you believe this to be a genuine Land Office Corner Yes

If not, why?

Walter Haberle

(Signature)

2/29/40

Project Asst.

(Date)


(Title) 21

FIELD LOCATION POSTER

CORNER OF THE PAINTED SQUARE

tree inches diameter, on the side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant. Give any further facts which will aid in finding this Corner again.

Metal Location Poster is on a \_\_\_\_\_ The bearing trees



(Make sketch of topography near Center)



U. S. Department of Agriculture  
FOREST SERVICE

C-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5<sup>th</sup> Mer.

1/4 Corner common to Sections  
4, and 5.


Corner consists of a Iron pipe (not) in place  
State condition new

Dimensions above ground 1" — 27" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species SPRUCES SPRUCES

Diameter 5" 4"

Bearing S. 63° E S. 11° W

Distance .24 .37

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

B. Albee

(Signature)

Leader


(Title)

1937

(Date)

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 R. 27 Mer. 5th