

U. S. Department of Agriculture

FOREST SERVICE

V-11

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

Quarter Corner common to Sections

21, and 23

Corner consists of a Brass cap on iron in place


State condition good

Dimensions above ground 18 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Handwritten signature: Jerome W. ...

June 1, 1935 (Date)


Handwritten signature: J. ...

125

Handwritten notes on a grid of dashed lines, mostly illegible.

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 147 N. R. 27 W. Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Posted
VII

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W Mer.

1/4 Corner common to Sections
28, and 33

Corner consists of a Brass Cap (~~not~~) in place
State condition Good

Dimensions above ground 13 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


W. Banks
(Signature)

9/10/34
(Date)

T. F.
(Title)

Corner again.
 Corner is located on flange
 west of cut foot Sioux Lake
 and North of Deer Lake. No
 witness trees. Mixed hardwood
 stand over topping few pine
 about 6 chs. north.

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 147N. R. 27W. Mer.

U. S. Department of Agriculture
FOREST SERVICE

CHIPPewa NATIONAL FOREST

P.
V-11

CORNERS OF THE PUBLIC SURVEY

T. 147th R. 27th 5th Mer.

Corner common to Sections
28, and 33

Corner consists of a brass cap on pipe (not) in place


State condition good

Dimensions above ground 18" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. J. Donohue
(Signature)
June 1, 1925
(Date)
J. J. Donohue
(Title)

Faint, illegible text on ruled lines at the top of the page.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147N. R. 27W. 5th Mer.