

U. S. Department of Agriculture  
FOREST SERVICE

P  
PK3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 27 W 5th Mer.

1/4 Corner common to Sections

20, and 21  
Corner consists of a Iron Pipe (not) in place



State condition new

Dimensions above ground 1' — 27" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch Ash

Diameter 6 4

Bearing N65°E 588°W

Distance 22 46

Do you believe this to be a genuine Land Office Corner? yes  
If not, why? \_\_\_\_\_


(Signature)

(Date)

(Title)

18

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.  
 Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147NR. 270 5th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

P-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 27 W 5th Mer.

Corner common to Sections

21, and 22

Corner consists of a Stone P (net) in place



State condition

Dimensions above ground 1 - 28 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species RP Bark

Diameter 1 1/2

Bearing 57° 45' W S 1° 45'

Distance 274 30

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

(Signature)

(Date)

(Title)

194

CORNER OF THE PUBLIC SURVEY

Give any further facts which will aid in finding this


corner distant.

from which this corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near corner)

U. S. Department of Agriculture  
FOREST SERVICE

P-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 27 W 5th Mer.

Corner common to Sections

21, and 22

Corner consists of a iron pipe (not) in place


State condition just erected

Dimensions above ground 1" - 28" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species NO. B.O. 25

Diameter 16 4

Bearing S 70° W S 34° E

Distance 224 50

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

(Signature)

(Date)

(Title)

84

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 142 N. R. 2 W. Mer. 5 1/2