

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

C13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147^N R. 27W 5th Mer.

Quarter Corner common to Sections

4, and 3

Corner consists of a Iron pipe (not) in place



State condition good

Dimensions above ground 1"12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N.P. N.P.

Diameter 10" 8"

Bearing N39.088E N75.3W

Distance 2.33 2.30

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Walter Haberle


12/8/39
 (Date)

(Signature)
 Project Asst.
 (Title)

Corner again.

Give any further facts which will aid in finding this
 ----- chains distant.
 ----- from which this Corner bears
 ----- side of
 ----- tree ----- inches diameter, on the

The bearing trees Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147N R. 27W 5th Mer.

U. S. Department of Agriculture
FOREST SERVICE

C-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.
Quarter

Corner common to Sections

4, and 3

Corner consists of a Iron pipe (not) in place



State condition Good

Dimensions above ground 1"12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION



DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species S N.P. N.P.

Diameter 10" 8"

Bearing N30.8E N75.3W

Distance 2.33 2.30

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Walter Haberle

(Signature)

Project Asst.

12/8/39

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a bearing trees



(Make sketch of topography near Corner)

T. 147N R. 27W 5th Mer.

U. S. Department of Agriculture
FOREST SERVICE

C-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147ⁿ R. 27^w 5th Mer.
Quarter Corner common to Sections

4, and 3
Corner consists of a Iron pipe (not) in place



State condition good

Dimensions above ground 1"12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147N
R27W
S3

T147N
R27W
S4

BT

BT

Species N.P. M.P.

Diameter 10" 8"

Bearing N30.08'E N75.4'W

Distance 2.33 2.30

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? _____

Walter Haberle

(Signature)

Project Asst.

12/8/39

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on 3 bearing trees



(Make sketch of topography near Corner)

T. 147N R. 27W 5th Mer.

U. S. Department of Agriculture
FOREST SERVICE

C-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. R7W 5th Mer.

1/4

Corner common to Sections

4, and 3

Corner consists of a Iron Pipe (not) in place


State condition Just E.

Dimensions above ground 9-27" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>53</u>	<u>54</u>		
<u>B.T.</u>	<u>B.T.</u>		

Species NO. NO.

Diameter 10" 8"

Bearing N 71.8° E N 75.7° W

Distance 2.33 2.30

Do you believe this to be a genuine Land Office Corner?

If not, why? yes

(Signature)

1936
(Date)

(Title)

16

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147 R. 27 S. 74. Mer.