

U. S. Department of Agriculture

FOREST SERVICE

C-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

1/4 Corner common to Sections 3, and 2


Corner consists of a iron pipe in place State condition

Dimensions above ground 1" - 32" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species JP NP

Diameter 6 5

Bearing N53.4E N64W

Distance 27 55

Do you believe this to be a genuine Land Office Corner?

If not, why?


(Signature)

(Date)

(Title)

11

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.
 Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 R. 27 S. 14 Mer.

U. S. Department of Agriculture
FOREST SERVICE

CITR

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

1/4 Corner common to Sections

3, and 2

Corner consists of a iron pipe (not) in place



State condition

Dimensions above ground 1" - 32" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species JP. NP.

Diameter 6" 5"

Bearing N 55 1/2 E N 67 W

Distance 27 55

Do you believe this to be a genuine Land Office Corner?


If not, why? *yes*

(Signature)

(Date)

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 R. 27 Mer. 3-4

Form 874-0—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY



5-17

T. 147N R. 21W 5th - Mer.

1/4 Corner common to Sections
3, and 2

Corner consists of a stone (not) in place
 State condition good


Dimensions above ground 1.5 inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species SP UP
 Diameter 6" 5"
 Bearing N55°E N65°E
 Distance 27 53

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)

(Date)

(Title)

