

U. S. Department of Agriculture
FOREST SERVICE

N19 A

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

1/4

Corner common to Sections

14, and 23

Corner consists of a Iron Pipe (not) in place



State condition just erected

Dimensions above ground 1" - 28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species J P N P

Diameter 6" 24"

Bearing S 32 30 E N 00 15 W

Distance 29 79

Do you believe this to be a genuine Land Office Corner? yes
If not, why?


(Signature)

1936
(Date)

(Title)

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147N R. 27W 5th Mer.

U. S. Department of Agriculture
FOREST SERVICE

N-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

1/4 Corner common to Sections
14, and 23

Corner consists of a Iron Pipe (not) in place



State condition just erected

Dimensions above ground 1" - 28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species J P N P

Diameter 6" 24"

Bearing S 32 1/2 E N 50 15 W

Distance 29 79

Do you believe this to be a genuine Land Office Corner? yes
If not, why? _____

(Signature)

1936
(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147N R. 27W 5th Mer.

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

N-19

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

1/4

Corner common to Sections

19 and 23

Corner consists of a stone (not) in place


State condition

Dimensions above ground 1 - 20 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of stone is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

SP NP

Diameter

6" 24"

Bearing

S 31° E N 09° 50'

Distance

29 79

Do you believe this to be a genuine Land Office Corner?

If not, why?

Yes


(Date)

(Title)

Faint, illegible text on ruled lines, possibly bleed-through from the reverse side of the page.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)