

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

*Copies  
 mailed  
 5/36  
 E21*

----- NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 147 R. 27 S. 5 Mer.

----- I ----- 2 ----- III ----- Corner common to Sections  
 -----, -----, -----, and -----

Corner consists of a ~~crude stake 5ft high~~ (not) in place  
 State condition -----

Dimensions above ground ----- inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.  
**CARDINAL POSITION** **DIAGONAL POSITION**

N	W	S	E

NW	SW	SE	NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and  
 fill blanks below, giving bearings from Corner to Trees and  
 Distances in Links.


Species -----

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

-----  
 -----

-----  
 (Signature)

-----  
 (Date)


-----  
 (Title)

CORNER OF THE BRICKS MARKED  
 24" WIDE BY 30" HIGH  
 CORNER BEARS  
 FROM WHICH THIS CORNER BEARS  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a

24" WIDE BY 30" HIGH  
 CORNER BEARS  
 FROM WHICH THIS CORNER BEARS  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a

Give any further facts which will aid in finding this  
 Corner again.

Give any further facts which will aid in finding this  
 Corner again.



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

172

T. Section R. Mer.

Section

Corner common to Sections

2, 1, and 12

Corner consists of a granite (rock) in place



State condition

Dimensions above ground 6 x 74 x 20 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species SP JP JP SP

Diameter 12" 14" 7" 9"

Bearing N 59° E S 10° E S 73 1/2° W N 73 1/2° W

Distance 154 72 63 49

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_


(Signature)

(Date)

(Title)

CORNER OF THE PUBLIC SURVEY

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chain distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

E-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 27 W 5th Mer.

Section 10 N Corner common to Sections  
2, 1, 11, and 12



Corner consists of a Concrete (not) in place  
State condition Just Erected

Dimensions above ground 6-24-20 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 147 N R 27 W S 1	S 12	S 11	S 2
B.T.	B.T.	B.T.	B.T.

Species J.P. J.P. J.P. J.P.  
 Diameter 12" 12" 9" 10"  
 Bearing N 50° E 517 N 53° E 573 N 42° W 236 W  
 Distance 154 72 63 46

Do you believe this to be a genuine Land Office Corner?

If not, why? yes

(Signature)


(Date)

(Title)

5

Metal Location Poster is on a \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)