

U. S. Department of Agriculture  
FOREST SERVICE

A21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. <sup>48</sup>147 N R. 27 W 5th Mer.

Section Corner common to Sections  
1, 2, 35, and 36



Corner consists of a Wood Stake (not) in place  
State condition Poor

Dimensions above ground 3" x 3" x 34" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? Not scribed. No B.T.'s located.

H. Norman  
(Signature)

Feb. 15, 1935 Tech. Foreman  
(Date) (Title)

Field Man (J. Henson - Enrollee)  
(Title)

Corner again.

Give any further facts which will aid in finding this


1.44 chains distant.

from which this Corner bears 58°W

side of

tree 6 inches diameter, on the SW

Metal Location Poster is on a Jack Pine



(Make sketch of topography near Corner)

T. 147N R. 27W Mer. 5th