

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST *Z-23*

CORNERS OF THE PUBLIC SURVEY

T. *147* R. *27* Mer. *5*



1/4 Corner Corner common to Sections
36, and *1*

Corner consists of a *Iron Post* in place
State condition *Not Corroded*

Dimensions above ground *2"-8"-28"* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *N.P.* *N.P.* *Querc*

Diameter *10"* *14"* *5"*

Bearing *N 43° E* *N 88° E* *S 70° E*

Distance *95* *63* *52*

Do you believe this to be a genuine Land Office Corner *Yes*

If not, why? _____

(Signature)

(Date)

(Title)

Give any further facts which will aid in finding this
Corner again.

Metal Location Poster is on a tree
Inches diameter, on the
side of
from which this Corner bears
chains distant.

<p>Sec. 1</p> <p>T-146N R-26W</p>	<p>Sec. 36</p> <p>T-147N R-27W</p>
<p>Sec. 1</p> <p>T-146N R-26W</p>	<p>Sec. 36</p> <p>T-147N R-27W</p>

(Make sketch of topography near Corner)

T-147N R-27W 576 Mer.

U. S. Department of Agriculture

FOREST SERVICE

2-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 22W 5th Mer.

Corner common to Sections

36, and 1

Corner consists of a I.P. (not) in place

State condition NW

Dimensions above ground 2' 5" 28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

		536	
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

7147 B27 536	7116 B27 51	7114 B27 51	
B27	B27	B27	

Species NP NP Birch

Diameter 10 14 8

Bearing N44SE N24SE N24SE

Distance 95 6.3 52

Do you believe this to be a genuine Land Office Corner?

If not, why?


(Signature)

(Date)

(Title)

131

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.
 Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 142 R. 27 Mer.