

U. S. Department of Agriculture
FOREST SERVICE

A-23

~~Chippewa~~ NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY



T. ¹⁴⁸147 N R. 27 W ²⁰5th Mer.

Quarter: Corner common to Sections
....., 1, and 36

Corner consists of a (not) in place
State condition

Dimensions above ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch

Diameter 8"

Bearing S. 47° E

Distance 0.10 ch.

Do you believe this to be a genuine Land Office Corner?

If not, why?


H. Norman
(Signature)

Feb. 13, 1935
(Date)

Tech. Foreman
(Title) J. Hanson
(Enrolled)

Field Work: J. Hanson

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147N. R. 27W. Mer. 574