

U. S. Department of Agriculture
FOREST SERVICE

P 24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5th Mer.

1/16#6

Corner common to Sections

24, and

Corner consists of Wood post (not) in place

State condition good

Dimensions above ground 4" 42 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

BT

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

| |
|--|
| |
|--|

Species J. pine

Diameter 8"

Bearing N 49 E

Distance .09

Do you believe this to be a genuine Land Office Corner? No

If not, why? County corner

Walter Haberle

(Signature)

11/29/39

(Date)

Leader

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a The berrying tree



(Makes sketch of topography near Corner)

T. 147 R. 27 Sth Mer.