

U. S. Department of Agriculture

FOREST SERVICE

P 25

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

Section 13, 18, 24, and 19  
 Corner common to Sections

Corner consists of a Con. Mon. (not) in place


State condition Just erected

Dimensions above ground 6" x 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 147N
R. 27
S. 18

T. 147N
R. 27
S. 13

T. 147N
R. 26
S. 24

--

B.T.
------

B.T.
------

B.T.
------

--

Species N.P. N.P. Cedar

Diameter 12" 15" 5"

Bearing N77E N62W S49W

Distance 39lks. 79lks. 34lks.

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? -----

-----

-----

-----

(Signature)


(Date)

(Title)

25

Blank lined area for notes at the top of the page.

Give any further facts which will aid in finding this corner again. Metal Location Poster is on a tree 8 inches diameter, on the side of ... from which this corner bears chains distant.



(Make sketch of topography near corner)

U. S. Department of Agriculture  
FOREST SERVICE

N-25

Chippewa NATIONAL FOREST


CORNERS OF THE PUBLIC SURVEY

T. 34TH R. 27W 5th Mer.

Section \_\_\_\_\_ Corner common to Sections  
15, 16, 24, and 19

Corner consists of a Con. Mon. (///) in place  
State condition Just erected


Dimensions above ground 6" x 2 1/2" inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species H.P. H.P. Cedar  
Diameter 12" 12" 8"  
Bearing N77E N65W S65W  
Distance 211.5 211.5 241.5

Do you believe this to be a genuine Land Office Corner? Yes  
If not, why? \_\_\_\_\_

(Signature) \_\_\_\_\_  
(Date) \_\_\_\_\_ (Title) \_\_\_\_\_

555

UNITED STATES GEOLOGICAL SURVEY

SECTION OF THE ...

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147 R. 27 Mer. 5-24

Form 874-0—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

N-25

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th—Mer.

Section Corner common to Sections 13, 18, 24, and 19

Corner consists of a Copper Nail (not) in place  
 State condition Just Erod

Dimensions above ground 6 X 2 X 30 inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 147 R 27 518	T 147 R 27 519	T 147 R 28 524	T 147N R 28W 513
BT	BT	BT	BT

Species	<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>12</u>	<u>6</u>	<u>8</u>	<u>12 1/2</u>
Bearing	<u>N41E</u>	<u>S50E</u>	<u>S25 1/2 W</u>	<u>N29 1/2 W</u>
Distance	<u>34</u>	<u>53</u>	<u>30</u>	<u>34</u>

Do you believe this to be a genuine Land Office Corner?

If not, why? Yes

(Signature)

(Date)

(Title)

1161

22

Section 19

Section 24

CORNER OF THE PUBLIC ROAD

Corner again

Give any further facts which will aid in finding this


corner distant

from which this corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near corner)

T. 192N

R. 27W

Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

N-25

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

Section 13, 18, 24, and 19 Corner common to Sections

Corner consists of a Con. Mon. (N) in place



State condition Just erected

Dimensions above ground 6" x 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION



DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



B.T.

B.T.

B.T.

Species N.P. N.P. Cedar

Diameter 12" 15" 5"

Bearing N77E N52W S40W

Distance 50Lks. 70Lks. 34Lks.

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why?

(Signature)


(Date)

(Title)

Handwritten mark

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 147 R. 27 Mer. 6-23