

U. S. Department of Agriculture
FOREST SERVICE

A+E-1

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 142N R. 27W S4- Mer.
McAuley Corner common to Sections

Corner consists of a Iron Pipe in place
State condition Just Erected

Dimensions above ground 1 1/2" x 1 1/2" x 1 1/2"
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

LONG	142	27	54	1/2
SECTION	27	27	27	27
ANG.	56	56	56	56
QUARTER	SW	SW	SW	SW
	NW	SW	SE	NE

Method of Iron Pipe is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearing from Corner to Trees and Distances in Links.

T147 R27 56	T147 R28 51		
B1	B1		

Species Red Oak
Diameter 10 1/2
Bearing S 70° E N 19° W
Distance 96 70

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

U.S. Department of Agriculture


FOREST SERVICE

CORNERS OF THE PUBLIC SURVEY

Corner consists of a ... in place

Diagonal position ...

North location ... on the



U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

marked Corner common to Sections
....., and to



Corner consists of a Iron Pipe (not) in place
State condition just started

Dimensions above ground 1 - 27 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

— Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Oak Poplar

Diameter 10" 10"

Bearing S-70° E N-19 3/4° W

Distance .96 .70

Do you believe this to be a genuine Land Office Corner? Y

If not, why?

C. H. D.
(Signature)

1936
(Date)

(Title)

U. S. Department of Agriculture
FOREST SERVICE

A to E-1

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. *147N* R. *27W* *5th* Mer.

~~Monahan~~ Corner common to Sections
....., and *4*

Corner consists of a *Iron Pipe* (not) in place



State condition *Just started*

Dimensions above ground *1 - 27* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

..... Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *White Top*

Diameter *10"* *10"*

Bearing *S-70° E* *N-19° W*

Distance *.96* *.70*

Do you believe this to be a genuine Land Office Corner? *Y*

If not, why?


Ch. D.
(Signature)

1930
(Date)

(Title)

(Make sketch of topography near Corner)

T. 40N R. 27W S. 34 - Mer.



Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

MC

#5 FROM
N

N SHOT

LOWER PIGEON

• • • • •