

U. S. Department of Agriculture
FOREST SERVICE

E-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142N R. 27W 5th Mer.

~~Meander~~ Corner common to Sections
6, and 7

Corner consists of a Iron Pipe (not) in place



State condition Just Erected

Dimensions above ground 1 7/8" x 2 7/8" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

5-6	5-7		
BT	BT		

Species Ash Ash

Diameter 5" 6"

Bearing N 53 1/8 W N 63 1/8 E

Distance 166 122

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?


(Signature)

1936
(Date)

(Title)

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147N R. 27W Mer. 5th

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

E-2-3

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 21W 5th Mer.

Monroe Corner common to Sections

6, and 7

Corner consists of a ~~Iron Pipe~~ (not) in place


State condition ~~just marked~~

Dimensions above ground 1" 2 1/2" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Ash Ash

Diameter 5" 6"

Bearing N 53 1/2 W N 63 1/2 E

Distance 166 122

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)

1936 (Date)

(Title)

Corner again.

Give any further facts which will aid in finding the


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 197N R. 27W Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST F-2.3
CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5th Mer.

Meander Corner common to Sections
6, and 7

Corner consists of a ~~iron pipe~~ (not) in place


State condition ~~just erected~~

Dimensions above ground 1-27 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

56	57		
117 3/4	117 1/4		

Species ~~Aspen~~ ~~Ash~~

Diameter ~~5"~~

Bearing ~~N 36° E~~ ~~N 74° E~~

Distance ~~53~~ ~~138~~

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

(Signature)

(Date)

(Title)

336

(Make sketch of topography near Corner)

	Sec.		Sec.
	Sec.		Sec.

Metal Location Poster is on a

tree _____ inches diameter, on the

side of _____

from which this Corner bears _____

chains distant.

Give any further facts which will aid in finding this

Corner again.

U. S. Department of Agriculture
FOREST SERVICE

EF-3
3 E
P E

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 47N R. 27W 5th Mer.

Meander Corner common to Sections
_____, _____, and _____

Corner consists of a stone (not) in place


State condition good

Dimensions above ground 1' - 7" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Red White

Diameter 5" 6"

Bearing N 53 1/2 W N 63 1/2 E

Distance 106 122

Do you believe this to be a genuine Land Office Corner?

If not, why?

Yes

(Signature)

(Date)


(Title)

336

Blank lined area for notes at the top of the page.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T 147N R 29W 6th - Mer.