

U. S. Department of Agriculture
FOREST SERVICE

E-4,5

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. *147N* R. *27W* *5th* - Mer.



Monroe Corner common to Sections
.....,, and *6*, and *7*

Corner consists of a *Iron Pipe* (not) in place
State condition *Just created*

Dimensions above ground *1" - 2 1/2"* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Red* *Red*

Diameter *6"* *5"*

Bearing *N 73 1/2° E* *N 71° N 1/2° E*

Distance *25'* *1.58*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

(Signature)

1986
(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R. Mer.