

U. S. Department of Agriculture
FOREST SERVICE

N-11, 12

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

22.0 Corner common to Sections

16, and 21

Corner consists of a ~~Iron Pipe~~ (not) in place



State condition ~~just treated~~

Dimensions above ground 1" 28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species SP NP

Diameter 5" 20"

Bearing N43°E S55°E

Distance 49 30

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____


(Signature)

(Date)

(Title)

656

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.
 Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147N R. 0327W 5TH Mer.