

U. S. Department of Agriculture

FOREST SERVICE

NATIONAL FOREST

R-4-15

CORNERS OF THE PUBLIC SURVEY

T. 147 N R 27 W Mer.

Meander - Corner transition to Sections

22, and 27

Corner consists of a Base cap on post in place

State condition Good

Directions above ground 1/2 in. 1/2 in. 1/2 in. 1/2 in. inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

North	South	East	West	NW	SW	SE	NE

Mound of stone is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Bearing N 90° W

Distance 350

Do you believe this to be a genuine Land Office Corner? Yes

If not, what is the reason? None

*[Handwritten signature]*

*[Handwritten text]*

CORNERS OF THE PUBLIC SURVEY

Township 27 N. Range 12 E. Section 36

Corner of Section 36 and Section 35

Corner of Section 36 and Section 37

Corner of Section 36 and Section 38

Diagonal line from corner of Section 36 to center of Section 37


Cardinal position of corner of Section 36

From which the corner bears  
side of

two inches diameter, on the

North location corner is on a

NW SE NE



Please see located  
Diagonal line from corner of Section 36 to center of Section 37

Sec.

36  
Diagonal line from corner of Section 36 to center of Section 37

Sec.