

U. S. Department of Agriculture  
FOREST SERVICE

T-U-1

*Angew* NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. *19N* R. *R2W* Sth. Mer.  
*Meander* Corner common to Sections

Corner consists of a *Iron P* in place  
State condition *25* and *30*

Dimension above ground *1 1/2* inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION

NE	40	40	40	40				
SE								
SW								
NW								

Mound of *Iron P* is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>T 147</i>	<i>T 147</i>		
<i>506</i>	<i>R 37</i>		
<i>BT</i>	<i>BT</i>		

Species *Corymbia ussuriensis*

Diameter *5"*

Bearing *192°W* *N 135°E*

Distance *357* *306*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? *Yes*

U.S. Department of Agriculture

FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 12N. R. 25W. S. 31

Section 31, Township 12 North, Range 25 West, Section 31

and

Corner consists of 2

Diagonal position

Diagonal position

Diagonal position

from which the Corner bears

tree

tree diameter on the

tree location

tree location

tree location

tree location

tree location

tree location

tree location

tree location

tree location

tree location

tree location

tree location

tree location

tree location

tree location

tree location

tree location

tree location